

# Safety Update: Safety Investigations

Fiscal and Management Control Board

May 10, 2021

Steven V. Culp, Chief Investigation and Safety Assurance Officer

## Investigation Training Accomplishments

#### **Training Module Name**

- 2. Employee Injury Response 14. Bus Transportation Familiarization
- 3. Safety Event Response Team (SERT) 15. Rail Transportation Familiarization
- 4. On-Scene Signals

  16. Rail Vehicle Maintenance
  - Familiarization
- 5. On-Scene MOW 17. On-Scene Safety Responder
- 6. On-Scene Power 18. Photographing the Scene Part A
- 7. On-Scene Bus Transportation 19. Photographing the Scene Part B
- 8. On-Scene Rail Transportation 20. Sketching the Scene
- 9. On-Scene Rail Vehicle Maintenance 21. Post-On-Scene Investigation Activities
- 10. Effective Interviewing 22. Causal Factors and Root Cause
  - Analysis
- 11. Signals Familiarization 23. Report Writing and Mitigating Actions
- 12. MOW Familiarization

#### <u>Training Roll Out</u>

- General Manager/Deputy General Manager
  - December 2020 Modules 1 & 2
- MBTA Safety Employees
  - January to April 2021 All Modules
- All MBTA Departments
  - April to June 2021 Area Specific Modules


Full Implementation of new Safety Event Investigation Manual to begin in July 2021

#### Investigation Team - Overview

- Past MBTA Safety was limited to only one (1) recognized Subject Matter Expert (SME).
- Past A majority of the department worked 1<sup>st</sup> shift hours and limited weekend coverage.
- *Present* MBTA Safety has added seven (7) SME's that cover multiple disciplines raising the level of expertise for investigations and field presence.
- Present MBTA Safety has 24/7 shift coverage including weekends.
- Fast Fact The five (5) member Overnight Safety Team has over 110 years of experience in their respective fields.

#### Investigation Team – Lead by Example

- Deputy Director Charles Murphy (33 yrs. exp.) –
   Overnight Team Field Manager
- Field Duty Christmas Eve, 2020, 3:30am: Roadway Hazard
- MBTA Safety identified a motor vehicle facing the wrong way in the Sullivan Square Upper
- The driver of the pickup truck was unresponsive and had his engine running with the shifter in drive
- Police blocked the vehicle, gained entry into the vehicle, woke the driver and moved the vehicle to a safe location.





## Investigation Team – Lead by Example

- Deputy Director Kathleen Murphy (18 yrs. exp.) –
   Daytime Team Field Manager
- Hot Line Call Monday, January 14, 2021, 1:11pm: Homeless groups built an encampment in the area near the Red Line.
- Employee safety concern for those accessing the Foot Gate to the Right Of Way (ROW).
- A swift and humane coordinated response from Safety, Transit Police, E&M, and Transportation ensured employee safety was prioritized, as the encampment along with any debris and trash were removed.
- As is standard practice, Transit Police offered those that are displaced transportation to a local shelter or medical facility where they can get the assistance that they need.





#### Investigation Team – Track

- Track Safety Lead Investigator (SLI) Amanda Fletemeyer (17 yrs exp) Overnight Team
- Emergency Response Thursday, December 17, 2021, 8:34am: Orange Line Wellington Yard weather-related derailment.
- SLI Fletemeyer heard over-the-air that a train derailed on the northside of the yard while working on the southside.
- MBTA Safety was on scene within 3 minutes and started the scene safety assessment and investigation.
- Due to the snow levels, the 3<sup>rd</sup> Rail was covered at key locations around the train. SLI Fletemeyer ensured MBTA Safety's 3<sup>rd</sup> Rail tester was placed in the power section to allow safe recovery and investigation efforts.





#### Investigation Team - Power


- Power SLI Chis Peach (20 yrs. exp.) Overnight Team
- Emergency Response Saturday, February 6, 2021, 4:30am: Fire and/or Smoke Event in a power utility room.
- SLI Peach heard of a fire event at a Red Line Traction Power Station 600 VDC transformer while monitoring radio transmissions.
- SLI Peach arrived on-site within 9 minutes to collect firsthand information of the event from the Power Department and Boston Fire.
- MBTA Safety updated key stakeholders that a 600 VDC breaker issue occurred during planned work.
- MBTA Safety was able to obtain real-time photographs and investigate extent of damage.





#### Investigation Team - Bus

- Bus SLI Ronnie Neff (22 yrs. exp.) Daytime Team
- Emergency Response Monday, January 25, 2021, 4:10am: Infrastructure Damage.
- SLI Neff responded to Forest Hills within 15 mins. for a pipe burst in the upper busway that created a slip, trip, and fall hazard for customer and employees.
- SLI Neff used his bus expertise to coordinate Officials and work crews to ensure bus, busway, and station egress safety,
- The areas were monitored and coned-off, as an E&M lift truck cleared the overhead hazards and sanded/salted the area while the plumbers repaired the broken pipe.



#### Investigation Team – Diversion Safety

- Light Rail SLI Thomas Maher (22 yrs. exp.) Day/Night Team
- Diversion Oversight Wednesday, February 17, 2021, 9:21pm: Green Line Construction Diversion Power Issue.
- SLI Maher was assisting with the implementation of an Early Access Diversion when a 600 VDC power issue interfered with the process.
- SLI Maher assisted in determining the live/dead power sections, offloading trains, shutting trains down, and a coordinating a bus shuttle.
- The diversion was canceled when it was determined the overall coordination would benefit from a stand down and after action.
- The next day, with all responsible parties debriefed and coordinated, a successful Early Access Diversion was implemented.



